U.S. Department of Transportation

United States Coast Guard

## LOCAL NOTICE TO MARINERS

COASTAL WATERS FROM EASTPORT, MAINE TO SHREWSBURY, NEW JERSEY

### **WEEKLY SUPPLEMENT**

\*\* Electronic Bulletin Board Service: (703) 313-5910 \*\* 300 to 28.8 bps, 8 data bits, no parity, 1 stop bit \*\* NIS watchstander, 24 hours a day at (703) 313-5900 \*\*

\*\* INTERNET ADDRESS \*\*
HTTP://www.navcen.uscg.mil
OR
FTP://ftp.navcen.uscg.mil

Weekly supplemental editions contain new information only available following the monthly edition. NOTE: Chart corrections and Light List changes appear only once each. A complete listing of current discrepancies and temporary changes appear in the monthly issue, LNM 24/97. Subscription to this weekly publication is free. If you have questions about the LNM or wish to be on the mailing list, contact:

COMMANDER, FIRST COAST GUARD DISTRICT (oan) 408 Atlantic Avenue, Boston, Massachusetts 02110-3350

Telephone (Day): 1-800-848-3942. To order LNM: Ext. 8335 (After 4:30 p.m. Ext. 7722) 24 Hour FAX: (617) 223-8073

Coast Guard's Customer Infoline (8:00 a.m. - 4:00 p.m.): 1-800-368-5647. Hearing impaired (TDD) 1-800 689-0816

All bearings are in degrees TRUE - All times are in Local Time unless otherwise noted.

NOTE: A vertical line in the RIGHT MARGIN of sections I, V, VI, VII indicates new information.

#### BROADCAST NOTICE TO MARINERS

The following Broadcast Notice to Mariners (BNM's) have been issued since last week:

First District CG1-0296 to 0308 Group Boston BOS-0055 to 0056

Group Long Island Sound LIS-0063 to 0070

Group Moriches MOR-0039 to 0043

Group New York NEW-0122 to 0125

Group Portland POR-0044 to 0045

Group Southwest Harbor SWH-0048 to 0052

Group Woods Hole WHO-0077 to 0080

Light List Reference: ATLANTIC COAST, VOLUME 1, COMDTPUB P16502.1, 1996 Edition

I SPECIAL NOTICES This section contains information of Special concern to the Mariner.

### RELOCATION OF THE NEW YORK BRIDGE BRANCH

The First Coast Guard District Bridge Branch has relocated to the Battery Park Building. Their new address is: Commander (obr), First Coast Guard District, Battery Park Bldg., New York, NY 10004-5073 LNM 25/97 (CGD1)

II DISCREPANCIES This section lists all discrepancies to Aids to Navigation reported and corrected since the last published list. A discrepancy is a change in the status of an aid to navigation that differs from what is published and or charted.

DISCREPANCIES (since last week)

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

\_\_\_\_\_

00265.00 MERRIMACK RIV ENT LWB MR LT EXT 13282 BOS-0055-97 25/97

00390.00 25/97	THE GRAVES LT	LT DIM		13270	CG1-03	301-97
00675.00 25/97	SHINNECOCK LT	LT EXT		12300	CG1-02	298-97
00930.00 02045.00 03740.00	DOG IS LT DI BAKER IS LT AREY LEDGES BY 4	LT EXT LT EXT BUOYSINK	13394 13321	SWH-0 SWH-0		25/97 25/97 SWH-
0048-97 12310.00 0056-97	25/97 SCITUATE HBR CH BY 9 25/97	MISSING RETF	RO		13269	BOS-
21420.00 0067-97	MATINECOCK PT SHL LGB 21 25/97	LT EXT	•		12363	LIS-
24785.00 25/97	SOUTHPORT LT 7	LT EXT		12369	LIS-006	66-97
30681.00 25/97	SHINNECOCK BAY LB 11	LT EXT		12352	MOR-0	043-97
34295.00 25/97	GERRITSEN IN LB 2	LT DIM		12350	NEW-0	

DISCREPANCIES CORRECTED

LLNR Name of Aid Status Chart BNM LNM affected Ref. Ref.

	<del> </del>							
01835.00	FRENCHMAN BAY APP LWB	FBE		RELIGI	HTED		13318	SWH
0047-97	24/97							
05965.00	SASANOA RIV BY 32		RESET	ON ST	ATION	13296	0042-9	7 POR
24/97								
07386.00	BASKET IS LB 4	RELIG	HTED		13288	POR-0	044-97	25/97
13865.00	STAGE HBR LB 1		RESET	ON ST	ATION	13237	WHO-0	079-9
25/97								
14525.00	HYANNIS HBR LB 4		RELIGH	HTED		13229	WHO-0	077-9
24/97								
15475.00	VINEYARD HAVEN LT 7		WATCH	HING PF	ROPERL	_Y	13233	WHC
0080-97	25/97							
19795.00	WATCH HILL LT		WATCH	HING PF	ROPERL	_Y	13205	WHC
0078-97	25/97							
23270.00	CONNECTICUT RIV RANGE	J FRNT L	_T	WATCH	HING PE	ROPERL	_Y	1237
LIS-0069-97	25/97							
23285.00	CONNECTICUT RIV LT 129		RELIGH	HTED		12377	LIS-006	65-97
25/97								
26125.00	PORT JEFFERSON APP LWE	3 PJ		WATCH	HING PE	ROPERL	_Y	1236
LIS-0068-97	25/97							
26870.00	COLD SPRING HBR LT		WATCH	HING PF	ROPERL	_Y	12365	LIS-
0070-97	25/97							
34885.00	AMBROSE CH LBB 14		WATCH	HING PF	ROPERL	_Y	12327	NEW
0125-97	25/97							
35035.00	SWASH CH RR LT		RELIGH	HTED		12327	NEW-0	124-9
25/97								
35755.00	SHREWSBURY RIV CH LB 5		WATCH	HING PF	ROPERL	_Y	12324	NEW
0122-97	24/97							
ØØØØØØØØØ	ØØØØØØØØØØØØØØØØØØØØØØØ	y g g g g g	y g g g g g	ØØØØØ	ØØØØ!	ØØØØØ	øgøøø!	ØØØØ

## **DISCREPANCIES (PRIVATE AIDS)**

LLNR Name of Aid Status Chart BNM LNM affected Ref. Ref.

#### NONE THIS WEEK

# **DISCREPANCIES (PRIVATE AIDS) CORRECTED**

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref

### **NONE THIS WEEK**

III TEMPORARY CHANGES - TEMPORARY CHANGES CORRECTED This section contains temporary changes and corrections to Aids to Navigation for the current week. When aids are temporarily relocated for dredging, a temporary correction shall be listed in Section IV giving the new position.

#### TEMPORARY CHANGES

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

20542.00 MYSTIC HBR BY 20 (SEE SECT IV) RELOCATE 13214 CG1-

0304-97 25/97

31560.00 EAST ROCKAWAY IN LT 11 (SEE SECT IV) RELOCATE 12352 CG1-

0306-97 25/97

#### TEMPORARY CHANGES CORRECTED

LLNR Name of Aid Status Chart BNM LNM

affected Ref. Ref.

03930.00 FOX ISLANDS THOROFARE LB 16 (SEE SECT IV) WATCHING PROPERLY 13308 CG1-0287-97 24/97

22300.00 WIGWAM RK BY 9 (SEE SECT IV) WATCHING PROPERLY 13213

CG1-0290-97 24/97

24000.00	NEW HAVEN HBR E ENT BY 5 (SEE SECT IV	') RELOCATE	12371		
CG1-0300-97	25/97				
31290.00	STATE BOAT CH LT 53 (SEE SECT IV)	RELOCATE	12352 CG1-		
0307-97	25/97				
AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA					

QQQQQQQQQQQQQQ

IV CHART CORRECTIONS This section conatains corrections to federal and private maintained Aids to Navigation, as well as NOS corrections.

This section contains corrective actions affecting chart(s). Corrections appear numerically by chart number, and pertain to that chart only. The mariner must decide which Chart(s) to correct.

The following example explains the individual elements of a typical chart correction.

	Chart	Chart	Edition	Last Local Notice	Horizontal	Source of	
Curre	ent Local						
	number	edition	date	to Mariners	Datum Reference	Correction	
Notice to Mariners							
	/	/	/	/	/	/	
/							
	13248	6 <sup>th</sup> ed. 09	/05/81 L	AST LNM 42/85	NAD 83	(CG1)	
(15/9)							
(Temp) MASSACHUSETTS - SEACOAST location							

Change: Fog signal of Buoy PR to WHISTLE 41o36 12.1N 69o51 17.1W Object of corrective Position (Degrees, minutes, seconds Corrective and tenths) action action The letter (M) immediately following the chart number indicates that the correction should be applied to the Metric side of the chart only. (Temp)indicates that the chart correction action is temporary in nature. Courses and bearings are given in degrees clockwise from 000 true. Bearings of light sectors are toward the light from seaward. The nominal range of lights is expressed in nautical miles (NM). 12350 55<sup>th</sup> ed., 06/24/95 LAST LNM 23/97 NAD 83 25/97 (TEMP) NEW YORK - JAMAICA BAY AND ROCKAWAY INLET (CGD01) Relocate East Rockaway Inlet Light 11 from (40<sup>2</sup>35'34.9"N, 73<sup>2</sup>44'53.0"W) to 40<sup>2</sup>35'35.3"N 073244'53.6"W 12352 27<sup>th</sup> ed., 02/03/96 LAST LNM 24/97 NAD 83 25/97 (TEMP) SHINNECOCK BAY TO EAST ROCKAWAY INLET (CGD01) Relocate State Boat Channel Daybeacon 66 from (40238'54.3"N, 73217'23.9"W) to 40<sup>2</sup>38'54.3"N 073217'24.1"W East Rockaway Inlet Light 11 from (40235'34.9"N, 73244'53.0"W) to 40235'35.3"N 073244'53.6"W (PERM) State Boat Channel Buoy 53 to State Boat Change Channel Light 53, FI G 4s, SG dayboards and relocate from (40238"50.0"N, 073219'30.6"W) to 40<sup>2</sup>38'50.3"N 073219'31.1"W 12354 35<sup>th</sup> ed., 01/04/97 LAST LNM 24/97 NAD 83 25/97 (TEMP) CT-NY-LONG ISLAND SOUND - EASTERN PART (CGD01) Relocate New Haven Harbor East Entrance Buoy 5 from (41214'25.8"N, 72254'17.1"W) to 41214'26.2"N

(Supercedes 40/96) 12354 35<sup>th</sup> ed., 01/04/97 LAST LNM 24/97 NAD 83

OT NIVI ONO IOLAND COLIND FACTEDN DADT

CT-NY-LONG ISLAND SOUND - EASTERN PART

(CGD01)

Relocate Wigwam Rock Buoy 9 from (41218'55.7"N,

72<sup>2</sup>11'47.7"W) to 41<sup>2</sup>18'55.3"N

25/97

25/97

072211'45.9"W

072254'14.4"W

(Supercedes 24/97)

12363 37<sup>th</sup> ed., 12/07/96 LAST LNM 16/97 NAD 83

NEW YORK - LONG ISLAND SOUND - WESTERN PART (NOAA HECK) Add Symbol for Wreck, submerged 44 feet 40255'03.6"N 073238'37.7"W Symbol for obstruction, submerged 48 feet 40255'22.4"N 073239'00.4"W Symbol for wreck, submerged 41 feet 40255'49.7"N 073237'31.4"W Symbol for Obstruction, submerged 35 feet 40<sup>2</sup>55'11.4"N 073<sup>2</sup>37'09.1"W Symbol for Wreck, submerged 34 feet 40254'10.3"N 073239'17.7"W Symbol for Obstruction, submerged 40 feet 40254'46.3"N 073241'57.0"W 12364 30<sup>th</sup> ed., 02/15/97 LAST LNM 13/97 NAD 83 25/97 (TEMP) NEW YORK AND CONNECTICUT - LONG ISLAND SOUND - PORT JEFFERSON (CGD01) Relocate New Haven Harbor East Entrance Buoy 5 from (41214'25.8"N, 72254'17.1"W) to 41214'26.2"N 072254'14.4"W (Supercedes 40/96) 12364 30<sup>th</sup> ed., 02/15/97 LAST LNM 13/97 NAD 83 25/97 NEW YORK AND CONNECTICUT - LONG ISLAND SOUND - PORT JEFFERSON (NOAA HECK) Symbol for Wreck, submerged 44 feet Add 40255'03.6"N 073238'37.7"W Symbol for obstruction, submerged 48 feet 40255'22.4"N 073239'00.4"W Symbol for wreck, submerged 41 feet 40255'49.7"N 073237'31.4"W Symbol for Obstruction, submerged 35 feet 40<sup>2</sup>55'11.4"N 073<sup>2</sup>37'09.1"W Symbol for Wreck, submerged 34 feet 40254'10.3"N 073239'17.7"W Symbol for Obstruction, submerged 40 feet 40254'46.3"N 073241'57.0"W 12367 21<sup>st</sup> ed., 10/19/96 LAST LNM 16/97 NAD 83 25/97 LONG ISLAND SOUND - WESTERN PART (NOAA HECK)

Symbol for Wreck, submerged 44 feet Add

40255'03.6"N 073238'37.7"W

Symbol for obstruction, submerged 48 feet

40255'22.4"N 073239'00.4"W

Symbol for wreck, submerged 41 feet

40255'49.7"N 073237'31.4"W

Symbol for Obstruction, submerged 35 feet

40255'11.4"N 073237'09.1"W

Symbol for Wreck, submerged 34 feet

40254'10.3"N 073239'17.7"W

Symbol for Obstruction, submerged 40 feet

40254'46.3"N 073241'57.0"W

12371 22<sup>nd</sup> ed., 07/25/92 LAST LNM 11/97 NAD 83

(TEMP) NEW HAVEN HARBOR

(CGD01)

Relocate New Haven Harbor East Entrance Buoy 5

from (41<sup>2</sup>14'25.8"N, 72<sup>2</sup>54'17.1"W) to 41<sup>2</sup>14'26.2"N

072254'14.4"W

12372 28<sup>th</sup> ed., 06/18/94 LAST LNM 24/97 NAD 83 25/97

(TEMP) WATCH HILL TO NEW HAVEN HARBOR - LONG ISLAND SOUND

(CGD01)

Relocate New Haven Harbor East Entrance Buoy 5

from (41<sup>2</sup>14'25.8"N, 72<sup>2</sup>54'17.1"W) to 41<sup>2</sup>14'26.2"N

072254'14.4"W

(Supercedes 40/96)

12372 28<sup>th</sup> ed., 06/18/94 LAST LNM 24/97 NAD 83 25/97

(TEMP) WATCH HILL TO NEW HAVEN HARBOR - LONG ISLAND SOUND

(CGD01)

Relocate Mystic Harbor Buoy 20 from

(41<sup>2</sup>19'47.9"N, 71<sup>2</sup>58'54.8"W) to 41<sup>2</sup>19'47.1"N

071258'54.6"W

Change Wigwam Rock Buoy 9, White and Orange can to Green Can 41²18'55.3"N 072²11'45.9"W

13006 29<sup>th</sup> ed., 03/22/97 LAST LNM 23/97 NAD 83 25/97

WEST QUODDY HEAD TO NEW YORK

(NOS SILVER SPRING, MD)

Add Racon symbol (magenta circle) to

Buzzards Bay Entrance Light 41°23'47.5"N

071220'00.6"W

13205 32<sup>nd</sup> ed., 10/07/95 LAST LNM 24/97 NAD 83 25/97

RI - CT - NY - BLOCK ISLAND SOUND

(CGD01)

Relocate Wigwam Rock Buoy 9 from (41218'55.7"N,

72<sup>2</sup>11'47.7"W) to 41<sup>2</sup>18'55.3"N

072211'45.9"W

(Supercedes 24/97)

13211 13<sup>th</sup> ed., 08/24/91 LAST LNM 24/97 NAD 83 25/97

NORTH SHORE OF LONG ISLAND SOUND - NIANTIC BAY AND VICINITY

(CGD01)

Relocate Wigwam Rock Buoy 9 from (41218'55.7"N,

72<sup>2</sup>11'47.7"W) to 41<sup>2</sup>18'55.3"N

072211'45.9"W

(Supercedes 24/97)

13214 25<sup>th</sup> ed., 10/01/94 LAST LNM 24/97 NAD 83 25/97

(TEMP) FISHER ISLAND SOUND

(CGD01)

Relocate Mystic Harbor Buoy 20 from

(41<sup>2</sup>19'47.9"N, 71<sup>2</sup>58'54.8"W) to 41<sup>2</sup>19'47.1"N

071258'54.6"W

13305 27<sup>th</sup> ed., 03/21/92 LAST LNM 24/97 NAD 83 25/97

PENOBSCOT BAY

(CGD01)

Relocate Fox Islands Thorofare Lighted Buoy 16

from (44<sup>2</sup>07'29.3"N, 68<sup>2</sup>52'25.2"W) to 44<sup>2</sup>07'29.5"N

068252'27.4"W

13308 11<sup>th</sup> ed., 10/31/92 LAST LNM 24/97 NAD 83 25/97

FOX ISLAND THOROFARE

(CGD01)

Relocate Fox Islands Thorofare Lighted Buoy 16

from (44<sup>2</sup>07'29.3"N, 68<sup>2</sup>52'25.2"W) to 44<sup>2</sup>07'29.5"N

068<sup>2</sup>52'27.4"W

V ADVANCE NOTICES This section contains advance notice of approved projects or upcoming temporary changes such as dredging, etc. Mariners are advised to use caution while transitting these areas.

MA - MARTHA'S VINEYARD TO BLOCK ISLAND - VINYEARD SOUND MAIN CHANNEL - The Coast Guard will make the following changes on or about 15 July in order to improve transit through Vineyard Sound Main Channel.

Relocate Middle Ground Lighted Bell Buoy 27 (LLNR 15575) to PA 41-28-28N, 070-41-07W.

Delete Naushon Lighted Bell Buoy 28 (LLNR 15585).

Add Vineyard Sound Lighted Whistle Buoy 29 (LLNR 15577) Green, FI G 4s, in PA 41-25-09N, 070-48-05W.

Delete Nashawena Lighted Whistle Buoy NA (LLNR 15595).

Add Vineyard Sound Lighted Bell Buoy 30 (LLNR 15597) Red, FI R 4s, in PA 41-24-00N, 070-50-11W.

Change Gay Head Lighted Gong Buoy 29 (LLNR 16605) to Gay Head Lighted Gong Buoy 31.

Add Vineyard Sound Lighted Whistle Buoy 32(LLNR 15613), Red, FI R 2.5s, in PA 41-22-05N, 070-57-25W.

Change Sow and Pigs Buoy 30 (LLNR 16617) to Sow and Pigs Buoy 34.

Change Sow and Pigs Lighted Bell Buoy 32 (LLNR 16618) to Sow and Pigs Lighted Bell Buoy 36.

Chart(s): 13218, 13230. LNM 25/97 (CGD1)

VI PROPOSED CHANGES This section contains notice of non approved, proposed projects open for comment. SPECIAL NOTE: Mariners are requested to respond in writing to: Commander, First Coast Guard District (oan), 408 Atlantic Avenue, Boston, MA 02110-3350, unless otherwise noted.

## PROPOSED WATERWAY PROJECTS OPEN FOR PUBLIC COMMENT

WATERWAY Closing Docket No. Ref. LNM

CT/NY - LONG ISLAND SOUND - The Coast Guard is conducting a Waterways Analysis and Management System study of Long Island SOund, including Stratford Shoal. The focus of this study is the areas's aids to navigation systemn, waterborne commerce, marine casualty information, port/harbor resources, emergency response plans, routine and emergency communication capabilities, and future developement projects. Our desire is to make this system as safe and effective as possible. Any company or individual wishing to provide comments or participate in a user survey should contact: Commandin Officer, USCGC JUNIPER (WLB 201), NECT Pier #2, Newport, RI. 02841, ATTN: Ens Brown, (401)841-6953. Comments must be received no later than 15 September 1997. Refer to Docket No. 01-97-009 when responding.

Chart(s) 12354, 12363 LNM 25/97 (CGD1)

VII GENERAL This section contains information of general concern to the mariner. Mariners are advised to use caution while transitting these areas.

FOR STANDARD MILITARY AND GENERAL SAFETY ZONES IN EFFECT SEE THE MONTHLY EDITION LNM 20/97

MA - OFF/SHORE - The U.S. Navy advises of daily firing exercises from 6:30 am to 7:30 pm, 16-22 June, 1997, in an area bounded by the following:  $41^202.5N$ ,  $70^242W$ ; to  $41^207N$ ,  $70^222W$ ; to  $41^205N$ ,  $70^210W$   $41^200N$ ,  $69^255W$ ; to  $40^248N$ ,  $69^236W$ ; to  $40^230N$ ,  $69^236W$ ; to  $40^230N$ ,  $70^242W$ , thence to beginning.

Chart(s): 13003, 13006, 13200 LNM 25/97 (CGD1)

NY/NJ - NEWARK BAY - Dredging is being done at the Newark Bay Confined DIsposal Facility until on or about 30 October, 1997. On scene will be the Dredge 54, which will be monitoring channels 13, 16 & 18. Mariners are advised to use caution while transitting the area.

Chart(s) 12337 LNM 25/97 (CGD1)

CT - FISHERS ISLAND SOUND - Shoaling has been reported in the vicinty of Mumford Cove Buoy 8 (LLNR 20935).

Chart(s) 13214 LNM 25/97 (CGD1)

NY - FIRE ISLAND INLET - The following uncharted aids have been restablished and relocated to mark best water: Fire Island Inlet Lighted Buoy 2 (LLNR 29120), 40²37'01.5"N, 073²18'56.1"W: Fire Island Inlet Lighted Buoy 4 (LLNR 29125) 40²37'19.2"N, 073²18'59.6"W: Fire Island Inlet Lighted Buoy 6 (LLNR 29130) 40²37'36.7"N, 073²19'03.5"W:

## LNM 25/97 (CGD1)

### **BRIDGE SECTION**

APPLICATIONS HAVE BEEN RECEIVED FOR COAST GUARD PERMITS FOR THE FOLLOWING BRIDGE CONSTRUCTION/RECONSTRUCTION PROJECTS:

BRIDGE WATERWAY MILE NOTICE# COMMENT PERIOD ENDS REF/LNM

MBTA Parker/Rowley NA PN-1-899 18 June 1997 24-97

Interested parties are requested to submit their views in writing, on the proposed bridge project, to the office of Commander (obr), First Coast Guard District, Bldg. 135A, Governors Island, NY, NY 10004-5073. Copies of Public Notices may also be obtained at this address.

MA - BEVERLY HARBOR - DANVERS RIVER - Channel Obstruction - The Beverly Harbormaster has reported an area of shallow water in the vicinity of the Old Rt 1A Bridge across the Danvers River at mile 0.0 between Beverly and Salem, MA. An area with only 3 feet at low tide has been observed. The Coast Guard is investigating this situation and will provide more information as it becomes available. Mariners are advised to exercise caution when transiting the area and contact the Beverly Harbormaster at (508) 921-6059 for further information.

Chart(s) 13275 LNM 25/97 (CGD1)

CT - LONG ISLAND SOUND - CONNECTICUT RIVER - Bridge Repairs - Repairs to the wedge drive system of the Route 82/Haddam swing bridge is in progress. To facilitate repairs, bridge will open only on schedule as follows: Mondays through Thursdays, 0630, 1330 and 2000; Fridays 0630, 1330, 2000 and 2330; Saturdays 0630, 0930, 1330, 1600, 2000 and 2330; Sundays 0630, 0930, 1330, 1600 and 2000. Commercial and emergency openings can be provided, by calling the bridge tender 2 hours in advance. This project is expected to be completed by 31 October 1997. Mariners are advised to plan accordingly, reduce wake and exercise caution when transiting the area.

Chart(s) 12375 LNM 25/97 (CGD1)

VIII LIGHT LIST CORRECTIONS

(1) (2) (3) (4) (5) (6) (7) (8)

No. Name and location Position Characteristic Ht Rng Structure Remarks

NONE THIS WEEK

MARINE EVENTS 1996/1997

Marine Events normally will be published only once. Please mark your calendars accordingly.

LOCATION DATE/S TIME EVENT/SPONSOR CHRT

# **JUNE**

NY-New York Yacht Club 06/18-21 1100-1700 New York Yacht Club 13223

NY-300 yds north of Bar Beach 06/21 2100-2230 Glenwood Fire Dept Fireworks

MA-Gloucester, Ma.; Inner Hbr 06/21 0900-1200 International Dory Races

No Channel, Wright's Fish Co-

to CG Station

RI-Block Island Sound 06/22-27 1000-1700 Storm Trisail Club 13217

CT-Bridgeporport, CT Seaside Park 06/27 2000-2230 The Barnum Festival Fireworks 12354,

12369

(Rain Date 06/28)

NY-350 yds northeast of 06/28 2100-2230 Fayhey Wedding Fireworks 12366

Sands Point, NY